



NOTES:
 1. REMOVE JUMPER JA TO PREVENT HANDSWITCH INITIATED MOTION



TERMINAL CONNECTIONS FOR REMOTE CONTROL:

CW	C-M
CCW	C-N
STOP	NONE

17-5112-200 A

SIZE:
A

THIS DOCUMENT IS A COPY AND IS NOT THE SOURCE DOCUMENT. INFORMATION IS SUBJECT TO CHANGE WITHOUT NOTICE. THE INFORMATION CONTAINED HEREIN IS COPYRIGHTED BY HAROLD BECK AND SONS, INC. CHANGES TO THE DOCUMENT ARE PROHIBITED. CONTACT A BECK SALES ENGINEER IF A CERTIFIED DRAWING IS REQUIRED.

HAROLD BECK & SONS INC

NEWTOWN INDUSTRIAL COMMONS NEWTOWN, PENNSYLVANIA 18940 USA

TITLE:
WIRING DIAGRAM GROUP 11-1X5/2X5/3X5/405/415/465
120 VOLT 0 AUX SWITCHES 1 POTENTIOMETER
CW/CCW

DRAWN: CHH 10-12-07	SCALE: NONE	DRAWING NO: 17-5112-200	REV: A
CHECKED: GMD 10/15/07		SHEET NO. 1 OF 1	
APPROVED: JHM 10/16/07			